

## FOLLOW-UP SERVICE INSPECTION REPORT

	Global Flags Unlimited, LLC
Manufacturer:	

Order Number: 4010565

Date: 16-Nov-2023



This report is for the exclusive use of Intertek's Client and is provided pursuant to the Certification Agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or an advertisement of the inspected/tested material, product or service must first be approved in writing by Intertek. This report by itself does not demonstrate that the material, product, or service is, or has ever been, eligible to bear an Intertek certification mark. Initial Factory Assessments and Follow up Services are for the purpose of assuring appropriate usage of the Certification mark in accordance with the agreement, they are not for the purposes of production quality control and do not relieve the Client of their obligations in this respect



545 East Algonquin Road Arlington Heights, IL 60005 Telephone: +1 847 439 5667

Facsimile: +1 866 262 2753 www.intertek.com

First day started at 11:25

## **ETL FOLLOW-UP SERVICE** INICDECTION DEDODT

INSPECTION REP	PURI
Manufacturer Global Flags Unlimited, LLC	Page 2 of 3
Factory Address 3600 Cantrell Industrial Court ACWORTH GA 30101	Time of Arrival: 10:30 am Departure: 11:15 am
Date 16-Nov-2023 (Day / Month / Year	) ☐ 1Qtr ☐ 2Qtr ☐ 3Qtr ☑ 4Qtr ☐ IPI/IFA☐ Other
Intertek Representative Laymond Drummond	Order Number 4010565

<u>Directions to Intertek Representative</u>: Verify that products comply with all items specified in the Listing Report/CDR and production line tests and procedures specified are being conducted. All variations should be noted on F1, F2, and F3B and conveyed by email to the Regional Follow-up Service Center Please write "Variance" on subject line of email

the Regional Follow-up Service Center. Freas	e write v	ariance o	in subject line of email.		
THE FOLLOWING ITEMS WERE REVIEWE	D WITH 1	THE MAN	UFACTURER:		
a. Is the use of listing label controlled?	Yes	No	f. Were changes, additions, options, accessories, etc. made to listed products?	Yes No No	
<ul> <li>b. Labeling Method:</li> <li>✓ Separable Labels (supplied by Intertek</li> <li>☐ Direct Imprint (by Client)</li> <li>☐ Both</li> </ul>	)	g. Have changes occurred to the manufacturing process or quality system that affects listed products	Yes No No		
c. Are product markings per Listing Report?	Yes	No 🗌	h. Were variations noted on the last inspection report?	Yes No No	
d. Is production line testing required?	Yes 🗸	No 🔙	If yes, has the client responded?	Yes No	
If yes: Is testing being performed as required?	Yes	No	Have all variations been resolved?  If yes, include details on F2.	Yes No	
Is equipment calibrated?	Yes	No	i. Has the procedure or records for customer complaints/field failures been reviewed?	Yes No No	
Proper functionality of test equipment was verified/witnessed?	Yes 🖊	No	j. Were there any reports of product failures resulting in personal injury or property damage?  If yes, include details on F2.	Yes No No	
e. Qty of ETL labeled product shipped since l	ast inspec	<ul><li>k. Have any products, approved for Intertek certification, been involved with a product recall or similar corrective action?</li><li>If yes, include details on F2.</li></ul>	Yes No No		
VARIANCES					
Number of variances found during this inspe (explain on the F2)	ection:0		Do any variances warrant a product hold?	Yes No No	
Variations accepted per phone/email comm	unication v	with:			
Variations NOT accepted per phone/email communication with:					
Labels removed by manufacturer?	'es 🗌	No 🗌			
I acknowledge receipt of a copy of this inspe		ort issued 5-Nov-	1	(	
Factory Representative's Signature	_ <del></del> 7	Date	Intertek Representative	's Signature	

Factory Representative's (printed name)





## ETL Follow-up Service Inspection Report

Manufacturer Global Flags Unlimited, LLC	Page 3 of 3
Listing Report No. 101534480ATL-001A Issue/Rev. Date	04-Jan-2019 Date 16-Nov-2023
	DAY / MONTH / YEAR
Product Flag Pole Luminaire	
Intertek Representative Laymond Drummond	Order No. 4010565

VN	24.05	ITES 6	C	OMPLIE	S	
	PAGE	ITEM	YES	NO	N/A	COMMENTS
						Production of FPB series
						Conducted the inspection with Shane Stroud shane@flaco.com
	1	All	<b>/</b>			Reference and Address
	2	All	<b>/</b>			Product Description
	3-6	All	<b>/</b>			Product Photographs
	7-8	All	/			Critical Components
	9				<b>/</b>	Critical Unlisted CEC Components- No Unlisted CEC components are used in this report.
	10	All	/			Critical Features- Listed Components, Markings, and Cautionary marking
	11-13	All	/			Illustrations
	14-15				/	Test Summary
	16		<b>/</b>			Correlation Page For Multiple Listings
	17	All	<b>/</b>			General Information
	18				<b>/</b>	Evaluation of Unlisted Component
	19	All	<b>/</b>			Manufacturing and Production Tests. Grounding Continuity Test required
	20	All				
						Revision Summary- 4-Jan-2019